

## 석면해체·제거 사업장의 석면비산 측정 결과보고서

접수번호		접수일		
제출인	상호(대표자) (주)아주환경연구소		사업자등록번호 104-86-25855	
	주소 서울특별시 송파구 송파로 66 9층 (전화번호:02-426-5310)			
건축물	건물명 심팩 봉신공장 개보수 공사중 석면철거공사		위치 인천광역시 서구 건지로 124	
	연면적(㎡)	3,038.88 ㎡	작업기간 2014.03.19.~2014.03.25	
	석면건축자재 [길이(m)·면적(㎡)·부피(㎡)] 텍스[422.75㎡], 밤라이트[244.48㎡], 슬레이트[4629.17㎡]			
측정기관	대표자 박재성		사업자등록번호 119-86-21981	
	주소 경기도 수원시 권선구 덕영대로 201호 [알엔에이컨설팅(주)]			
측정일시	2014.03.19.~2014.03.25			
측정결과 -별첨-	시료번호	측정 지점	측정 결과(f/cc)	검출 석면

측정 지점 위치(도식도)

-별첨-

「석면안전관리법」 제28조제2항 및 같은 법 시행규칙 제38조제2항에 따라 석면해체·제거 사업장의 석면 비산 측정 결과를 제출합니다.

2014 년 04월 일

제출인

(주)아주환경연구소



인천 서구청장

귀하

첨부서류	「산업안전보건법 시행규칙」 별지 제17호의6서식의 석면해체·제거작업 신고서 사본	수수료 없음
------	--	-----------

1. 측정결과

측정일시	2014.03.19		
측정결과	시료번호	측정 지점	측정 결과(f/cc)
	20140319-1	부지경계선1	0.0008
	20140319-2	부지경계선2	0.0013
	20140319-3	부지경계선3	0.0010
	20140319-4	부지경계선4	0.0016
	20140319-5	위생설비	0.0007
	20140319-6	음압기1	0.0008
	20140319-7	음압기2	0.0007
	20140319-8	음압기3	0.0009
	20140319-9	음압기4	0.0010
측정일시	2014.03.20		
측정결과	시료번호	측정 지점	측정 결과(f/cc)
	20140320-1	부지경계선1	0.0015
	20140320-2	부지경계선2	0.0010
	20140320-3	부지경계선3	0.0009
	20140320-4	부지경계선4	0.0014
	20140320-5	위생설비7	0.0019
	20140320-6	음압기1	0.0010
	20140320-7	음압기2	0.0014
	20140320-8	음압기3	0.0005
	20140320-9	음압기4	0.0010
측정일시	2014.03.21		
측정결과	시료번호	측정 지점	측정 결과(f/cc)
	20140321-1	부지경계선1	0.0004
	20140321-2	부지경계선2	0.0003
	20140321-3	부지경계선3	0.0003
	20140321-4	부지경계선4	0.0005
	20140321-5	위생설비	0.0008
	20140321-6	작업장주변-실외	0.0012

<b>측정일시</b>	2014.03.22		
<b>측정결과</b>	<b>시료번호</b>	<b>측정 지점</b>	<b>측정 결과(f/cc)</b>
	20140322-1	부지경계선1	0.0004
	20140322-2	부지경계선2	0.0004
	20140322-3	부지경계선3	0.0005
	20140322-4	부지경계선4	0.0006
	20140322-5	위생설비	0.0006
	20140322-6	작업장주변-실외	0.0004
<b>측정일시</b>	2014.03.23		
<b>측정결과</b>	<b>시료번호</b>	<b>측정 지점</b>	<b>측정 결과(f/cc)</b>
	20140323-1	부지경계선1	0.0006
	20140323-2	부지경계선2	0.0006
	20140323-3	부지경계선3	0.0005
	20140323-4	부지경계선4	0.0004
	20140323-5	위생설비	0.0021
	20140323-6	작업장주변-실외	0.0016
<b>측정일시</b>	2014.03.24		
<b>측정결과</b>	<b>시료번호</b>	<b>측정 지점</b>	<b>측정 결과(f/cc)</b>
	20140324-1	부지경계선1	0.0002
	20140324-2	부지경계선2	0.0001
	20140324-3	부지경계선3	0.0003
	20140324-4	부지경계선4	0.0002
	20140324-5	위생설비	0.0016
	20140324-6	작업장주변-실외	0.0011

<b>측정일시</b>	2014.03.25		
<b>측정결과</b>	<b>시료번호</b>	<b>측정 지점</b>	<b>측정 결과(f/cc)</b>
	20140325-1	부지경계선1	0.0004
	20140325-2	부지경계선2	0.0004
	20140325-3	부지경계선3	0.0005
	20140325-4	부지경계선4	0.0006
	20140325-5	위생설비	0.0008
	20140325-6	작업장주변-실외	0.0014
	20140325-7	폐기물반출구	0.0014

## 2. 측정 사진

### 1) 2014.03.19



20140319-1 부지경계선1




20140319-2 부지경계선2



20140319-3 부지경계선3



20140319-4 부지경계선4



20140319-5 위생설비




20140319-6 음압기1



20140319-7 음압기2



20140319-8 음압기3



20140319-9 음압기4


2) 2014.03.20



3) 2014.03.21



2014.03.22



4) 2014.03.23




5) 2014.03.24




### 3. 측정위치도

#### 1) 2014.03.19.




현장소재지	도면명	평면도	측정 일자	2014-03-19
인천광역시 서구 건지로 124	축 적	No Scale	작성 일자	2014-03-19
공장 2층	작성자	이 은 정	도면 번호	건지로124-01

#### 2) 2014.03. 20.



현장소재지	도면명	평면도	측정 일자	2014-03-20
인천광역시 서구 건지로 124	축 적	No Scale	작성 일자	2014-03-20
공장 2층	작성자	이 은 정	도면 번호	건지로124-02

# 공장 옥탑



현장소재지	도면명	평면도	측정 일자	2014-03-20
인천광역시 서구 건지로 124	축 적	No Scale	작성 일자	2014-03-20
공장 옥탑	작성자	이 은 정	도면 번호	건지로124-03

### 3) 2014.03. 21.

20140321-01  
부지경계선 1

20140321-06  
작업장 주변 외기

20140321-02  
부지경계선 2

20140321-05  
위생설비

20140321-03  
부지경계선 3


20140321-04  
부지경계선 4

벽체 슬레이트


21일 석면해체제거 대상 지붕 슬레이트

현장소재지	도면명	평면도	측정 일자	2014-03-21
인천광역시 서구 건지로 124	축 적	No Scale	작성 일자	2014-03-21
공장 지붕 슬레이트	작성자	이 은 정	도면 번호	건지로124-04


3) 2014.03. 22.



4) 2014.03. 23.



4) 2014.03. 24.



4) 2014.03. 25.

